



WILDBEAR

From



Ultralight Castor Correction Arm Information Sheet BA 7626

Radius arm bush information

Genuine Discovery Series II radius arm bushes are recommended.

Axle End: Part Number RBX101680

Chassis End: Part Number RBX101730

Castor correction.

Your castor corrected radius arms have been computer designed to correct the alteration made to the steering geometry that occurs when a suspension lift kit is fitted to a vehicle. It is important to remember that when fitting lifted suspension a number of original factory settings will be altered including a raised centre of gravity, Altered steering geometry (which will affect road handling), Prop shaft angles.

Fitting a lift kit is not without consequence as a result of these items and you should always inform your insurer of any modifications made to the vehicle. It is also worth noting that whilst correcting one issue another may manifest itself. This can be the case when fitting castor corrected arms to return the steering back to standard but can induce prop shaft vibration in certain circumstances. This can be rectified by using high angle prop shafts, or double yolk props for extreme lifts.



Bearthmach
Est. UK 1958
LAND ROVER PARTS

Parts and Accessories for all Land Rovers



Head office: Bearmach Limited, Bearmach House, Unit 8, Pantglas Industrial Estate, Bedwas, Caerphilly, CF83 8GE
Tel: +44 (0)29 20 856550 Fax: +44 (0)29 20 865586 Email: bearthmach@bearthmach.com Web: www.bearthmach.com